CXS Nürnberg

High-visibility vest

Item number: 110-30-001; 110-30-002



PPE CATEGORY II

The high-visibility vest makes workers more visually noticeable in the working environment.

Material	**100 % Polyester**
Colours	
Sizes	**S/M, L/XL, XXL/3XL, 4XL/5XL**
Country of origin	**China**
Fabric weight	**120 g/m²**
Sales unit	**Piece**
Manufacturer	**CANIS SAFETY a.s.**

Protection and standards

EN ISO 13688:2013+A1:2021	General requirements for protective clothing
EN ISO 20471:2013+A1:2016	High-visibility clothing · class 2

Care

Wash at a maximum of 40 °C, mild process. Maximum 25 wash cycles for the high-visibility function. Rinse cold and spin briefly. Do not use biological detergents. Do not bleach. Do not tumble dry. Do not iron. Do not dry clean. Do not use fabric softener. If necessary, clean reflective strips with a soft cloth or sponge and mild detergent at a maximum of 40 °C; Rinse with clean water and dry completely.

Product overview based on manufacturer documents. Refer also to the original instructions and EU declaration of conformity.