CXS Braunschweig high-visibility

Work trousers

Item number: 110-35-099; 110-35-100; 110-35-101; 110-35-102; 110-35-103; 110-35-104; 110-35-105; 110-35-106



PPE CATEGORY I

Stretch allows the trouser fabric to follow movement.

Material	**98 % cotton, 2 % elastane**
Colours	
Sizes	**46, 48, 50, 52, 54, 56, 58, 60, 62, 64, 66, 68**
Country of origin	**China**
Fabric weight	**250 g/m²**
Sales unit	**Piece**
Manufacturer	**CANIS SAFETY a.s.**

Protection and standards

EN ISO 13688	General requirements for protective clothing
OEKO-TEX STANDARD 100	

Care

Wash at a maximum of 40 °C, normal process. Do not bleach. Do not tumble dry. Iron at a maximum of 150 °C. Do not dry clean. Do not iron reflective elements or knee reinforcements. Wash before first wear.

Product overview based on manufacturer documents. Refer also to the original instructions and EU declaration of conformity.