CXS Abrak gloves with nitrile coating

Nitrile assembly gloves

Item number: 110-50-009



PPE CATEGORY II

Nitrile foam covers the fingers and palm where parts are held.

Material	**Polyester** **Coating: nitrile**
Colour	
Sizes	**6, 7, 8, 9, 10, 11, 12**
Country of origin	**China**
Sales unit	**Pair**
Manufacturer	**CANIS SAFETY a.s.**

Performance levels to EN 388

Abrasion resistance	●●●●	**4 of 4**
Cut resistance (Coupe)	●○○○○	**1 of 5**
Tear resistance	●●○○	**2 of 4**
Puncture resistance	●○○○	**1 of 4**
Cut resistance (TDM)		**X - no rated level**

EN 388	Mechanical risks · 4121X
EN 420	General requirements for protective gloves

Care

Do not wash. Do not bleach. Do not tumble dry. Do not iron. Do not dry clean. Remove dirt with a soft brush. Dry damp gloves at room temperature away from heat sources. Replace worn, burnt, heavily soiled or hardened gloves.

Product overview based on manufacturer documents. Refer also to the original instructions and EU declaration of conformity.