CXS Halle

High-visibility jackets

Item number: 110-25-053; 110-25-054



PPE CATEGORY II

A detachable holder sits in the right chest pocket.

Material	**Base material: 60 % cotton, 40 % Polyester** **Additional material: 60 % cotton, 40 % Polyester**
Colours	
Sizes	**48, 50, 52, 54, 56, 58, 60, 62, 64, 66, 68**
Country of origin	**China**
Fabric weight	**280 g/m²**
Sales unit	**Piece**
Manufacturer	**CANIS SAFETY a.s.**

Protection and standards

EN ISO 13688:2013+A1:2021	General requirements for protective clothing
EN ISO 20471:2013+A1:2016	High-visibility clothing
OEKO-TEX STANDARD 100	

Care

Wash at a maximum of 40 °C, mild process. Maximum 25 wash cycles for the high-visibility function. Rinse cold and spin briefly. Do not use biological detergents. Do not bleach. Do not tumble dry. Iron at a maximum of 110 °C. Do not iron reflective elements. Do not dry clean. Do not use fabric softener. Do not use optical brighteners. If necessary, clean reflective strips with a soft cloth or sponge and mild detergent at a maximum of 40 °C; Rinse with clean water and dry completely. Wash before first wear and wash inside out.

Product overview based on manufacturer documents. Refer also to the original instructions and EU declaration of conformity.