CXS Bergheim M

Welding gloves

Item number: 110-50-028-11



PPE CATEGORY III

Cotton fabric forms the inner layer next to the hand.

Material	**Outer material: Aramid** **Back of hand outside: aluminium** **Intermediate layer: wool** **Inner layer: cotton**
Colour	
Sizes	**11**
EAN number	**8591940000943**
Country of origin	**Czechia**
Weight	**0.38 kg per pair**
Sales unit	**Pair**
Manufacturer	**CANIS SAFETY a.s.**

Protection and standards

EN 388	Mechanical risks
EN 420	General requirements for protective gloves
EN 407	Thermal risks (heat and/or fire) · 4244X4

Care

Do not wash. Do not bleach. Do not tumble dry. Do not iron. Do not dry clean. Inspect seams and the outer layer before every use; Remove damaged gloves from service. Avoid wet and greasy working environments. Store dry and protected from sunlight.

Product overview based on manufacturer documents. Refer also to the original instructions and EU declaration of conformity.